

Street Sweeper Summary Data (Revised 10/5/16 at 2:00 pm)

Project ID	Type of Improvement			Sweeper Service Description																Is sweeper service within 4 miles of a PM10 Monitor?	Requested CMAQ Funding
				Arterial Roadway				Collector Roadway				Residential Roadway				Other Roadway					
	Sweeper Replacement	Coverage Expansion	Increased Sweeper Frequency	Days between sweeping	Ln Miles Swept per Cycle	ADT per Lane	Service Area (Miles)	Days between sweeping	Ln Miles Swept per Cycle	ADT per Lane	Service Area (Miles)	Days between sweeping	Ln Miles Swept per Cycle	ADT per Lane	Service Area (Miles)	Days between sweeping	Ln Miles Swept per Cycle	ADT per Lane	Service Area (Miles)		
BKY_17-SW-001 REV	Yes	Yes	No	13	16	5,053	16	13	12	2,314	12	13	171	1,205	13	0	0	0	0	Yes, monitor 1, located at 26449 W 100th Drive, Buckeye AZ 85326	209,983
CHN_17-SW-001	Yes	No	No	0	0	-		30	43	2,837		30	493	88		0	0	0	0	Monitor 13	241,383
GLN_17-NW-001	No	Yes	Yes	0	0	-		60	494	3,000		60	1428	350		15	57	3100	57	MAP ID: 3, Site ID: 4032001, Name: Glendale, Address: 6001 West Olive Avenue, City: Glendale	253,396
MES17_SW-001	Yes	No	No	0	0	-		0	0	-		30	435	400		0	0	0	0	Yes, monitor #15 and/or #32	267,883
MES17_SW-002	Yes	No	No	0	0	-		0	0	-		30	387	400		0	0	0	0	Yes, monitor #15 and/or #32	267,883
PHX_17-SW-001	Yes	No	No	14	32	8,800		14	25	5,000		90	20	500		0	0	0	0	Yes, the sweeper to be replaced is part of a fleet that sweeps in our Central sweeping area as shown as 35-6 on the attached map. It is within four miles of PM-10 monitors. 10, 8, 5 and 3.	240,526
PHX_17-SW-002	Yes	No	No	14	32	8,800		14	25	5,000		90	20	500		0	0	0	0	Yes, the sweeper to be replaced is part of a fleet that sweeps in our Southwest sweeping area as shown as 35-5 in the attached map. It is within four miles of PM-10 monitors: 4, 5, 6, 7, 8, 9, and 11	240,526
TOL_17-SW-001	Yes	No	Yes	7	39	5,600		7	18	800		7	42	75		0	0	0	0	No.	245,492