

Agency:	Scottsdale		Title of Project:	Scottsdale Rd and Palm Lane	
Date:	10/24/2019				
Contact Name and Title:		Phone:	E-Mail:		
Sam Taylor, Traffic Engineering Analyst		480-312-2526	staylor@scottsdaleaz.gov		
Roadway Safety Program (RSP) Project Scope					
1. Describe your safety improvement project in detail: (50 words or less)					
1a.	The purpose of this project is to provide a safe and controlled location for pedestrians to cross Scottsdale Road near Palm Lane. There is a crash history along with existing and future development to warrant the improvement.				
2. Describe the project location, include pertinent demographic and land development information:					
2a.	The location is on Scottsdale Road at Palm Lane, approximately a quarter mile north of the signalized intersection at McDowell Road and a quarter mile south of the signalized intersection at Oak Street. There is existing commercial and residential development within the vicinity of the project and a future apartment complex planned on the east side of Scottsdale road just north of Palm Lane.				
3	For projects on State System:	BMP: (Begin Milepost)	N/A	EMP: (End Milepost)	N/A
4.	What network screening method was used to identify this project? <input type="checkbox"/> MAG <input type="checkbox"/> ADOT <input checked="" type="checkbox"/> Other (Below)				
4a	This location was identified as a top priority by Scottsdale's pedestrian crossing prioritization scoresheet.				
5. Was this project identified as a recommendation in a study? If so, what kind? (check all that apply)					
5a	<input type="checkbox"/> RSA <input type="checkbox"/> PA <input type="checkbox"/> SRTS Study <input checked="" type="checkbox"/> LASS Study <input type="checkbox"/> Other				
6.	Was the project identified using an agency adopted predictive safety analysis? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
7. What is the safety justification for the proposed project?					
7a	There was a fatal pedestrian/vehicle crash in 2019 and current and future development have initiated multiple requests for a pedestrian safety improvement at this location.				
8. Is Public outreach required for your project? If "yes" Provide what was done, the date(s) and outcomes. (Attach documentation if applicable)					
8a	The city will provide educational resources to instruct drivers how to respond to a pedestrian hybrid beacon.				
9. What safety related public education will your agency be providing before placing the safety improvement in service, if applicable?					
9a	Educational tools will be available online to citizens.				
10. Equity: Input the largest percent for each element for the one-mile radius or offset (Click on the hyperlinks in the text to open maps. See directions on side on maps):					
	65 yrs and Older	Minority Groups	No Vehicle Households	Disabled	Living in Poverty
10a	16.50%	25%	25%	13.56%	25%
11.	Avg Daily Traffic (ADT) Volume:	37,600	Year Collected:	2019	
12.	Total Crash Frequency:	29	Crash Rate (MVM or MEV):	0.4	
13.	What is the posted speed limit?	40 mph	Benefit/Cost:	39.2	

PROJECT COST ESTIMATE WORKSHEET

(Cost Estimates Are Required Regardless of Programming)

	REQUESTED PROGRAMMING (Complete if Item will be programmed in the MAG TIP)	Location Description	Pedestrian Hybrid Beacon Scottsdale Road at Palm Lane				
		Work Description	Install a Pedestrian Hybrid Beacon with a High Visibility Crosswalk				
		Funding Source	Local				
		Preferred Year to Program Work	2019				
COST ESTIMATE FOR DESIGN			UNITS	QUANTITY	UNIT COST	TOTAL	
DESIGN	PRELIMINARY ENGINEERING (15% plans) (Required for Budget)	Topographic Survey	LS	1	2,600.00	\$ 2,600.00	
		Design Concept Report (DCR)	LS	1		\$ -	
		Federal Project Environmental Determination	LS	1		\$ -	
		HAZMAT Assessment	LS	1		\$ -	
		SUBTOTAL - PRELIMINARY ENGINEERING COSTS					\$ 2,600.00
	FINAL DESIGN (30, 60, 95, 100% plans) (Required for Budget)	Plans, Specifications, Cost Estimates, Bidding	LS	1	16,357.00	\$ 16,357.00	
		Staff Time	LS	1	7,210.00	\$ 7,210.00	
		Drainage Report	LS	1		\$ -	
		SWPPP	LS	1		\$ -	
		SUBTOTAL - FINAL DESIGN COSTS					\$ 23,567.00
	TOTAL PRELIMINARY ENGINEERING AND DESIGN COST AVAILABLE FOR PROGRAMMING						\$ 26,167.00
	CONSTRUCTION	REQUESTED PROGRAMMING (Complete only if Construction will be programmed in the MAG TIP)	Location Description	Pedestrian Hybrid Beacon Scottsdale Road at Palm Lane			
			Work Description	Install a Pedestrian Hybrid Beacon with a High Visibility Crosswalk			
			Funding Source	RSP			
			Preferred Year to Program Work	2020			
COST ESTIMATE FOR CONSTRUCTION			UNITS	QUANTITY	UNIT COST	TOTAL	
CONSTRUCTION (Required for Budget)	Construction Surveying	LS	1	2,500.00	\$ 2,500.00		
	Relocate Sign W/ New Post & Post Base	EA	1	500.00	\$ 500.00		
	Relocate Water Meter, Cos 2330 & 2345	EA	2	1,500.00	\$ 3,000.00		
	Remove Ac Pavement	SY	89	25.00	\$ 2,222.22		
	Remove Concrete ADA Ramp	EA	1	1,500.00	\$ 1,500.00		
	Remove Concrete Sidewalk, Driveways & Slabs	SF	400	5.00	\$ 2,000.00		
	Remove Curb & Gutter	LF	75	10.00	\$ 750.00		
	Remove Dg	SF	180	1.25	\$ 225.00		
	Remove Light Pole	EA	1	1,500.00	\$ 1,500.00		
	Remove Pull Box	EA	1	523.35	\$ 523.35		
	Remove Traffic Markings 4" Equiv, Cos Suppl, Spec 350	LF	59	4.25	\$ 248.63		
	Sawcut & Match Existing	LF	250	2.00	\$ 500.00		
	Dust Control	LS	1	2,500.00	\$ 2,500.00		
	Haul Off	CY	10	50.00	\$ 500.00		
	Subgrade Preparation	SY	133	7.50	\$ 1,000.00		
	Swppp	LS	1	1,500.00	\$ 1,500.00		
	Traffic Control	WK	4	1,500.00	\$ 6,000.00		
	Pavement Replacement, Cos 2200	SY	89	75.00	\$ 6,666.67		
	Concrete Sidewalk (Mag Det. 230)	SF	400	7.00	\$ 2,800.00		
	Concrete Sidewalk Ramp, Cos 2232 (Modified-6' Wide)	EA	1	1,500.00	\$ 1,500.00		
	Concrete Sidewalk Ramp, Cos 2233 Type "A"	EA	1	3,000.00	\$ 3,000.00		
	Vertical Curb & Gutter, Cos 2220 Type "A"	LF	75	20.00	\$ 1,500.00		
	White Stripe 90Mil Thermo Plastic 4" Equiv	LF	415	3.50	\$ 1,452.50		
	Led Luminaire (1300K) (Horizontal Mount)	EA	1	1,000.00	\$ 1,000.00		
	Mast Arm (20 Ft.) (Tapered)	EA	1	1,750.00	\$ 1,750.00		
	Control Cabinet	EA	1	5,000.00	\$ 5,000.00		
	Controller (Type 170)	EA	1	5,000.00	\$ 5,000.00		
	Electrical Conduit (Its)	LF	10	50.00	\$ 500.00		
	Electrical Conduits - 2-3" (Traffic Signal)	LF	275	25.00	\$ 6,875.00		
	Foundation - (A - Pole)	EA	1	1,000.00	\$ 1,000.00		
	Foundation - (R - Pole)	EA	2	2,500.00	\$ 5,000.00		
	Hawk Signals	EA	6	2,500.00	\$ 15,000.00		
	Mast Arm 40' For Signal Pole (Sr Pole)	EA	1	4,000.00	\$ 4,000.00		
	Mast Arm 50' For Signal Pole (Sr Pole)	EA	1	4,500.00	\$ 4,500.00		
	Meter Service Pedestal	EA	1	4,500.00	\$ 4,500.00		
No. 7 Pull Box - Traffic Signal	EA	6	500.00	\$ 3,000.00			
Ped Crossing Signals	EA	1	2,500.00	\$ 2,500.00			
Pedestrian Push Button	EA	2	750.00	\$ 1,500.00			
Pole (Type A)	EA	1	1,000.00	\$ 1,000.00			

PROJECT COST ESTIMATE WORKSHEET
(Cost Estimates Are Required Regardless of Programming)

	Pole (Type Q)	EA	1	6,000.00	\$ 6,000.00
	Pole (Type R)	EA	1	7,000.00	\$ 7,000.00
	Traffic Signal Conductors Per The Approved Plans And Specifications.	LF	285	40.00	\$ 11,400.00
	Traffic Signal Mounting Assembly (Type I)	EA	6	195.00	\$ 1,170.00
	Traffic Signal Mounting Assembly (Type V)	EA	2	550.00	\$ 1,100.00
	Utility Locate - Pothole	LS	1	5,000.00	\$ 5,000.00
	SUBTOTAL - CONSTRUCTION COST				\$ 139,183.36
MOBILIZATION AND ADMINISTRATION COSTS	CONTRACTOR MOBILIZATION (Typically 8% of construction cost)			8%	\$ 11,134.67
	TRAFFIC CONTROL (0-8% of construction cost)			5%	\$ 6,959.17
	CONSTRUCTION CONTINGENCIES (Typically 5% of construction cost)			5%	\$ 6,959.17
	CONSTRUCTION ADMINISTRATION (Averaging 18% of construction cost)			15%	\$ 20,877.50
	SUBTOTAL - MOBILIZATION & ADMINISTRATION COSTS				\$ 45,930.51
TOTAL UTILITIES, CONSTRUCTION AND MOBILIZATION FOR PROGRAMMING					\$ 185,113.87
TOTAL COST ESTIMATE					\$ 211,281

Budget and Signature Page

Please describe the agency programming of this project in the agency's CIP	The city will use operational funding provided for traffic signal design, maintenance and construction as the matching funds.				
Phase	Location Description	Work Description	Year to be Programmed	Funding Source	Amount
Design	Pedestrian Hybrid Beacon Scottsdale Road at Palm Lane	Install a Pedestrian Hybrid Beacon with a High Visibility Crosswalk	2019	Local	\$ 26,167
Construction	Pedestrian Hybrid Beacon Scottsdale Road at Palm Lane	Install a Pedestrian Hybrid Beacon with a High Visibility Crosswalk	2020	RSP	\$ 185,114
Total Cost					\$ 211,281

Signature: To be signed with printed hard copy that is sent to MAG

As the jurisdiction's manager/administrator or designated representative, I certify that the information contained in this application is accurate and complete and that the local funds for this project will be included in the Lead Agency's local current CIP/TIP or budget document if the project is selected for MAG Roadway Safety Program funding. I also certify the Lead Agency's commitment to maintain or operate the facility.

Signature: 

Name: Philip H. Kercher

Title: Traffic Engineering and Operations Manager

Date: 10/31/19

RSP Application Benefit-Cost Tabulation Sheet

Agency:	Scottsdale	Title of Project:	Scottsdale Rd and Palm Lane
----------------	------------	--------------------------	-----------------------------

Annual Benefit Tabulation

Severity	Annual Average	Estimated CRF* Reduction	Total Reduction	Unit Cost	Annual Benefit
Fatal	0.20	57%	0.11	\$9,515,371	\$1,080,946
Incapacitating Injury	0.00	57%	0.00	\$550,499	\$0
Non-Incapacitating	0.00	57%	0.00	\$149,132	\$0
Possible Injury	0.00	57%	0.00	\$103,145	\$0
Total Annual Benefits					\$1,080,946

Costs

Total Project Cost	\$211,281
Project Life (years)	20
Interest Rate (%)	8%
Capital Recovery Factor	0.1019
Annual Construction Cost	\$21,519
Annual Maintenance Cost	\$6,000.00
Total Annual Costs	
\$27,519	

Benefit / Cost

Annual Benefit	Annual cost	Benefit / Cost Ratio
\$1,080,946	\$27,519	39.2

List CMF(s) Used in the field below and its associated countermeasure(s)

CMF ID: 9021 - Install pedestrian hybrid beacon (PHB or HAWK) with advanced yield or stop markings and signs. CMF = 0.432 for Vehicle/pedestrian crashes and all severity types.

Scottsdale		Scottsdale Rd and Palm Lane										RSP App V1_2019																
Incident ID	Incident Date & Time	Incident On Road	Incident Crossing Feature	Incident Offset	Incident Injury Severity Description	Incident First Harmful Description	Incident Collision Manner Desc	Incident Light Condition Desc	Incident Weather Desc	Incident Intersection Type Desc	Incident Junction Relation Desc	Incident Traffic Way Type Desc	Unit Travel Direction Desc	Unit Action Desc	Unit Road Condition Desc1	Unit Surface Condition Desc1	Unit Env Condition Desc1	Unit Defect Desc1	Unit Number	Unit Event Sequence Desc1	Unit Event Sequence Desc2	Unit Event Sequence Desc3	Unit Event Sequence Desc4	Person Type Desc	Person Safety Device Desc	Person Violation Desc1	Person Physical Desc0	
319448	1/31/2017 5:12:00 PM	07 GRANADA RD	Scottsdale Rd		0 No Injury	Motor Vehicle In Transport	Head On	Daylight	Clear	T Intersection	Intersection Non Interchange	Two Way Not Divided With Continuous Left Turn Lane	4 - West	Going Straight Ahead	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances	0	1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Unknown	0 - No Apparent Influence	
3206980	3/11/2017 1:29:00 PM	07 SCOTTSDALE RD	Palm Ln		200 Possible Injury	Motor Vehicle In Transport	Rear End	Daylight	Clear	Not At An Intersection	Not Junction Related	Two Way Not Divided With Continuous Left Turn Lane	2 - South	Going Straight Ahead		0 Dry	Stopped Parked Vehicle		0	1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Unknown	0 - No Apparent Influence	
3228585	5/3/2017 12:25:00 PM	07 SCOTTSDALE RD	Palm Ln		-20 No Injury	Motor Vehicle In Transport	Rear End	Daylight	Clear	Unknown	Not Junction Related	Two Way Divided Unprotected Painted 4 Feet Median	1 - North	Going Straight Ahead	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Speed To Fast For Conditions	0 - No Apparent Influence	
3253593	7/10/2017 1:00:00 PM	07 SCOTTSDALE RD	Granada Rd		-106 No Injury	Motor Vehicle In Transport	Left Turn	Daylight	Clear	Not At An Intersection	Not Junction Related	Two Way Not Divided With Continuous Left Turn Lane	1 - North	Making Left Turn	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Failed To Yield Right Of Way	0 - No Apparent Influence	
3255830	7/19/2017 12:11:00 PM	07 SCOTTSDALE RD	Granada Rd		-15 Suspected Minor Injury	Motor Vehicle In Transport	Rear End	Daylight	Clear	T Intersection	Intersection Related Non Interchange	Two Way Not Divided	1 - North	Going Straight Ahead	Unknown	Dry	Unknown	Unknown		1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Speed To Fast For Conditions	0 - No Apparent Influence	
3281944	9/28/2017 8:30:00 PM	07 SCOTTSDALE RD	Palm Ln		0 No Injury	Motor Vehicle In Transport	Sideswipe Same Direction	Dark Lighted	Clear	T Intersection	Intersection Non Interchange	Two Way Not Divided With Continuous Left Turn Lane	2 - South	Changing Lanes	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Unsafe Lane Change	0 - No Apparent Influence	
3386949	6/19/2018 3:14:00 PM	07 PALM LN	Scottsdale Rd		0 No Injury	Motor Vehicle In Transport	Angle (Front To Side)(Other Than Left Turn)	Daylight	Clear	T Intersection	Intersection Non Interchange	Two Way Divided Unprotected Painted 4 Feet Median	3 - East	Making Left Turn	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Made Improper Turn	0 - No Apparent Influence	
3409377	8/11/2018 4:52:00 PM	07 SCOTTSDALE RD	Granada Rd		-400 No Injury	Motor Vehicle In Transport	Angle (Front To Side)(Other Than Left Turn)	Daylight	Clear	Not At An Intersection	Not Junction Related	Two Way Divided Unprotected Painted 4 Feet Median	3 - East	Making Left Turn	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Made Improper Turn	0 - No Apparent Influence	
3409363	8/16/2018 12:10:00 PM	07 SCOTTSDALE RD	Palm Ln		300 No Injury	Motor Vehicle In Transport	Left Turn	Daylight	Clear	Not At An Intersection	Not Junction Related	Two Way Not Divided With Continuous Left Turn Lane	2 - South	Making Left Turn	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Failed To Yield Right Of Way	0 - No Apparent Influence	
3462228	11/28/2018 3:20:00 PM	07 SCOTTSDALE RD	Granada Rd		-15 No Injury	Motor Vehicle In Transport	Sideswipe Same Direction	Daylight	Clear	Four Way Intersection	Intersection Related Non Interchange	Two Way Divided Unprotected Painted 4 Feet Median	1 - North	Changing Lanes	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport	Curb			0 Driver	Air Bag Deployed/Shoulder-Lap Belt	Unsafe Lane Change	0 - No Apparent Influence	
2852947	3/7/2014 12:23:00 PM	07 SCOTTSDALE RD	Palm Ln		198 No Injury	Motor Vehicle In Transport	Rear End	Daylight	Clear	Not At An Intersection	Not Junction Related	Two Way Divided Unprotected Painted 4 Feet Median	2 - South	Going Straight Ahead	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Speed To Fast For Conditions	0 - No Apparent Influence	
2881787	8/13/2014 9:56:00 PM	07 SCOTTSDALE RD	Palm Ln		200 No Injury	Motor Vehicle In Transport	Left Turn	Dark Lighted	Clear	Not At An Intersection	Not Junction Related	Two Way Not Divided With Continuous Left Turn Lane	3 - East	Making Left Turn	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Unknown	Failed To Yield Right Of Way	0 - No Apparent Influence	
2891158	9/12/2014 8:33:00 PM	07 SCOTTSDALE RD	Palm Ln		0.1 Suspected Minor Injury	Motor Vehicle In Transport	Rear End	Dark Lighted	Clear	Unknown	Not Junction Related	Two Way Not Divided With Continuous Left Turn Lane	1 - North	Going Straight Ahead	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Speed To Fast For Conditions	0 - No Apparent Influence	
2925570	12/30/2014 3:44:00 PM	07 SCOTTSDALE RD	Granada Rd		200 No Injury	Motor Vehicle In Transport	Rear End	Daylight	Clear	Not At An Intersection	Not Junction Related	Two Way Divided Unprotected Painted 4 Feet Median	1 - North	Going Straight Ahead	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Speed To Fast For Conditions	0 - No Apparent Influence	
2940343	1/29/2015 5:22:00 PM	07 SCOTTSDALE RD	Palm Ln		0 Possible Injury	Motor Vehicle In Transport	Left Turn	Daylight	Rain	T Intersection	Intersection Interchange	Two Way Not Divided With Continuous Left Turn Lane	4 - West	Making Left Turn		0 Wet	Stopped Parked Vehicle		0	1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Made Improper Turn	0 - No Apparent Influence	
2959097	5/6/2015 4:23:00 PM	07 PALM LN	Scottsdale Rd		0 No Injury	Motor Vehicle In Transport	Rear End	Daylight	Clear	Four Way Intersection	Intersection Non Interchange	Two Way Divided Positive Median Barrier	4 - West	Backing	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Unknown	Other	0 - No Apparent Influence	
2973521	6/23/2015 9:24:00 AM	07 SCOTTSDALE RD	Granada Rd		-500 No Injury	Motor Vehicle In Transport	Sideswipe Same Direction	Daylight	Clear	Not At An Intersection	Not Junction Related	Two Way Divided Unprotected Painted 4 Feet Median	8 - Southeast	Entering Parking Position	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	No Improper Action	0 - No Apparent Influence	
2978754	7/16/2015 8:55:00 AM	07 SCOTTSDALE RD	Palm Ln		-145 Possible Injury	Motor Vehicle In Transport	Angle (Front To Side)(Other Than Left Turn)	Daylight	Clear	Not At An Intersection	Not Junction Related	Two Way Divided Unprotected Painted 4 Feet Median	4 - West	Making U Turn	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Air Bag Deployed	Failed To Yield Right Of Way	0 - No Apparent Influence	
3011472	9/15/2015 12:39:00 PM	07 SCOTTSDALE RD	Granada Rd		-90 Possible Injury	Motor Vehicle In Transport	Rear End	Daylight	Clear	T Intersection	Intersection Related Non Interchange	Two Way Not Divided	1 - North	Going Straight Ahead	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Speed To Fast For Conditions	0 - No Apparent Influence	
3036618	12/4/2015 6:30:00 PM	07 SCOTTSDALE RD	Granada Rd		-25 No Injury	Motor Vehicle In Transport	Rear End	Dark Lighted	Clear	Unknown	Crossover Related	Two Way Divided Unprotected Painted 4 Feet Median	1 - North	Changing Lanes	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Made Improper Turn	0 - No Apparent Influence	
3057750	1/8/2016 12:31:00 PM	07 SCOTTSDALE RD	Palm Ln		-50 No Injury	Motor Vehicle In Transport	Rear End	Daylight	Cloudy	Not At An Intersection	Not Junction Related	Two Way Not Divided With Continuous Left Turn Lane	1 - North	Going Straight Ahead	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Unknown	Speed To Fast For Conditions	0 - No Apparent Influence	
3057849	1/18/2016 4:21:00 PM	07 SCOTTSDALE RD	Palm Ln		200 No Injury	Motor Vehicle In Transport	Rear End	Daylight	Clear	Not At An Intersection	Not Junction Related	Two Way Not Divided With Continuous Left Turn Lane	2 - South	Going Straight Ahead	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Air Bag Deployed	Speed To Fast For Conditions	0 - No Apparent Influence	
3052267	2/2/2016 6:33:00 PM	07 PALM LN	Scottsdale Rd		0 Possible Injury	Motor Vehicle In Transport	Left Turn	Dark Lighted	Clear	T Intersection	Intersection Non Interchange	Two Way Not Divided With Continuous Left Turn Lane	3 - East	Making Left Turn	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Air Bag Deployed	Failed To Yield Right Of Way	0 - No Apparent Influence	
3057836	2/16/2016 4:29:00 PM	07 SCOTTSDALE RD	Palm Ln		-400 Suspected Serious Injury	Motor Vehicle In Transport	Angle (Front To Side)(Other Than Left Turn)	Daylight	Clear	Not At An Intersection	Not Junction Related	Two Way Not Divided With Continuous Left Turn Lane	3 - East	Making Right Turn		0 Dry	Stopped Parked Vehicle		0	1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Failed To Yield Right Of Way	0 - No Apparent Influence	
3092906	5/17/2016 8:14:00 AM	07 SCOTTSDALE RD	Granada Rd		-230 No Injury	Motor Vehicle In Transport	Sideswipe Opposite Direction	Daylight	Clear	Unknown	Driveway	Two Way Divided Unprotected Painted 4 Feet Median	6 - Northeast	Making Left Turn	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Drove Rode In Opposing Traffic Lane	0 - No Apparent Influence	
3102027	5/25/2016 10:42:00 AM	07 SCOTTSDALE RD	Palm Ln		0 No Injury	Motor Vehicle In Transport	Rear End	Daylight	Clear	T Intersection	Intersection Non Interchange	Two Way Divided Unprotected Painted 4 Feet Median	1 - North	Going Straight Ahead	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport				0 Driver	Shoulder And Lap Belt	Speed To Fast For Conditions	0 - No Apparent Influence	
3147099	10/2/2016 8:00:00 AM	07 SCOTTSDALE RD	Granada Rd		89 No Injury	Utility Pole Light Support	Single Vehicle	Daylight	Rain	Not At An Intersection	Not Junction Related	Two Way Not Divided With Continuous Left Turn Lane	2 - South	Unknown	Unknown	Wet	Unknown	Unknown		1 Utility Pole Light Support				0 Driver	Unknown	Drove Rode In Opposing Traffic Lane	4 - Alcohol	
3152661	11/5/2016 6:32:00 PM	07 SCOTTSDALE RD	Palm Ln		75 Suspected Minor Injury	Pedalcycle	Other	Dark Lighted	Clear	Not At An Intersection	Not Junction Related	Two Way Not Divided With Continuous Left Turn Lane	2 - South	Other	No Contributing Circumstances	Dry	No Contributing Circumstances	No Contributing Circumstances		0	1 Motor Vehicle In Transport				0 Pedalcyclist	None Used	Other	0 - No Apparent Influence
3490801	1/9/2019 6:25:00 PM	SCOTTSDALE RD	Granada Rd		10 Fatality	Pedestrian	Other (Pedestrian)	Dark Lighted	Clear	T Intersection	Intersection Related Non Interchange	Two Way Not Divided With Continuous Left Turn Lane	3 - East	Crossing Road	Other (Dark Clothing)	Dry	No Contributing Circumstances	No Contributing Circumstances		1 Motor Vehicle In Transport	Pedestrian			0 Pedestrian	Not Applicable	Failed To Yield Right Of Way	0 - No Apparent Influence	



